

Annexure- D

BUILDING SAFETY CERTIFICATE

No. 104/Camp/AG-IV/24-25

Dated: 15/10/24

It is certified that the existing building Mount hill Academy (name of the building or premises) at Chandanvan Mathura (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	<u>03</u> <u>(1G+2 floor)</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>

The building is owned/occupied by Mount hill Academy (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Public works department (Name of Department/ Govt.) on 15/10/24 (date of inspection) in the presence of Principal Mount Hill Academy Chandanvan, Mathura (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 15/10/24 for a period of 02 years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 15/10/24 at Mathura by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature Ramesh Kumar Sharma

Name: Assistant Engineer

Designation: _____

Name & Address of Department/ Office: CD-1. PWD. Mathura